

ND6000

When your ND6000 dye laser system arrives, contact Continuum immediately if there is damage to the crates or boxes. If no damage is evident, unpack and move the laser system to your lab, consulting the Installation section of your laser manual for details. After unpacking, again check for visible damage and call Continuum to schedule your installation.

Continuum asks that you have the equipment and materials listed below available during installation. These items will also be useful for operating and maintaining your system later. Please contact us in the Service Department of our Santa Clara office if you cannot provide all of them.

- Laser goggles (1 pair per person)
- Methanol, 1 gallon (4 liters), reagents grades or better
- Chemical Gloves
- 5 standard 110 VAC Receptacles
- 100-800 ml Glass Beaker
- Hemostats
- Lens tissue paper
- Kentek Zap It Burn Paper
- Power meter, 10-30 watt, with volume Absorber Detector Head
- Rhodamine 590 Perchlorate, >500 mg
- Mini Mag Lite and Inspection mirror (Dental type)

If you have any questions or would like additional information, please don't hesitate to call our Technical Support Dept @ (877)272-7783.
