

PANTHER EX OPO

When your PANTHER EX OPO system arrives, contact Continuum immediately if there is damage to the crates or boxes. If no damage is evident, unpack and move the OPO system to your lab, consulting the Installation sections of your manuals for details. After unpacking, again check for visible damage and call Continuum to schedule your installation.

Continuum asks that you have the equipment and materials listed below available during installation. These items will also be useful for operating and maintaining your system later. Please contact us in the Service Department of our Santa Clara office if you cannot provide all of them.

- Laser safety glasses
- Methanol, 50 ml, reagents grade or better
- Distilled water, 1.5 gallons (6 liters)
- 200-220 V single phase power, 8 amp service, and a plug to fit your outlet
- Kentek Zap It Burn Paper
- Power meter, 10 watt, with volume absorbing detector
- Monochromator, low resolution
- Lens Tissue
- Hemostats
- Mini Mag Lite and Inspection mirror (Dental type)

If you have any questions or would like additional information, please don't hesitate to call our Technical Support Dept @ (877)272-7783.
