

SURELITE I AND II

When your Surelite laser system arrives, contact Continuum immediately if there is damage to the crates or boxes. If no damage is evident, unpack and move the laser system to your lab, consulting the Installation section of your laser manual for details. After unpacking, again check for visible damage you begin your installation.

You should have the equipment and materials listed below available during installation. These items will also be useful for operating and maintaining your system later.

- Laser safety glasses
- Methanol, 50 ml, reagents grades or better
- Distilled water, 1.5 gallons (6 liters)
- 200-220 V single phase power, 8 amp service, and a plug to fit your outlet
- Kentek Zap It Burn Paper
- Power meter, 10 watt, with volume absorbing detector
- Mini Mag Lite and Inspection mirror (dental type)
- IR phosphor card
- Lens tissue paper

If you have any questions or would like additional information, please don't hesitate to call our Technical Support Dept @ (877)272-7783.
