

SURELITE OPO

When your SURELITE OPO system arrives, contact Continuum immediately if there is damage to the crates or boxes. If no damage is evident, unpack and move the OPO system to your lab, consulting the Installation sections of your manuals for details. After unpacking, again check for visible damage and call Continuum at (408) 727-3240 ext. Service to schedule your installation.

Continuum asks that you have the equipment and materials listed below available during installation. These items will also be useful for operating and maintaining your system later. Please contact us in the Service Department of our Santa Clara office (408-727-3240) if you cannot provide all of them.

- Laser safety glasses (1 pair per user)
- Methanol, 50 ml, reagents grade or better
- 1 standard 110 V outlet if system purchased with motor control option
- Kentek Zap It burn paper
- Power meter, 10 watt, with volume absorbing detector
- Monochromator, low resolution or spectrometer
- Lens tissue paper
- Mini Mag Lite and Inspection mirror (Dental Type)

If you have any questions or would like additional information, please don't hesitate to call our Technical Support Department at (877) 272-7783.
